



S0001884 - Kit for removing the broken filament of a teddy bear glow plug

Price with TAX	2 915.37 zł
Price	2 370.22 zł
Availability	Na zamówienie - 48h
Shipping time	48 hours
Number	S0001884
EAN code	5904966408793

Product description

HDI M8 x 1 / M9 x 1 / M10x1 / M10 x 1.25 / Toyota D4D M10 x 1.25 / 1.6 HDI NGK plugs and other

Set contains:

- hammer
- Drill and severe filament spark plug M10 x 1 mm
- Tap into the broken filament spark plug M10 x 1 mm
- Adapter for pulling and severe filament glow plug M10 x 1 mm
- Guide adapters in slot glow plug M10 x 1.00 mm
- Drill and severe filament spark plug M10 x 1.25 mm
- Tap into the broken filament spark plug M10 x 1.25 mm
- Adapter for pulling and severe filament glow plug M10 x 1,25 mm
- Guide adapters in slot glow plug M10 x 1.25 mm - drill and severe filament candle M8 x 1 mm
- Tap into the broken filament candle M8 x 1 mm
- Adapter for pulling and severe filament glow plug M10 x 1,25 mm
- Guide adapters in slot glow plug M8 x 1 mm
- Drill and severe filament candle x1 mm M9
- Tap into the broken filament candle M9 x 1 mm
- Guide adapters in the glow plug socket M9 x 1 mm
- Adapter for pulling the filament glow plug and severe M9 x 1 mm
- Tap into the broken filament candle M8 x 1 mm NGK spark
- Drill the broken filament candle M8 x 1 mm NGK spark
- Adapter for pulling and severe filament glow plug M8 x 1 mm NGK spark
- Guide adapters in slot glow plug M8 x 1 mm NGK spark

Application:

Cars:

CDI

1,6 HDI Peugeot, Citroen, Mazda, Ford, Fiat, Volvo, Mini,
Toyota D4D

1.3 Multi Jet Fiat, Fiat Ducat 2.3 / 3.0 Fiat Grande Punto M9 x 1 mm

DINING Mercedes E 211 S Clas, Sprinter, Vito after 2005 Engines - OM 642 V6 capacity of 2.2 / 3.0 / 3.2 - OM 651 after 2009
220 CDI, 200 CDI